ZITHA TECH SPECIALTY CABLES (Pty) Ltd

Increase the optical power meter



Overview

Optical power meters usually display time-averaged power. So for pulse measurements, the signal must be known to calculate the peak power value. However, the instantaneous peak power must be less than the maximum meter reading, or the detector may saturate, resulting in wrong average readings. Also, at low pulse repetition rates, some meters with data or tone detection may produce improper or no readings. A class of "high power" meters has some type of optical attenuating element.

Key Takeaways

To increase the optical power reading, ensure clean connectors, correct wavelength settings, proper calibration, and minimal insertion loss in the fiber link.Key Steps to Optimize Optical Power Readings



© 2026 ZITHA TECH SPECIALTY CABLES (Pty) Ltd - All rights reserved

1. Clean Connectors Thoroughly Dirty or contaminated connectors are the most common cause of low readings. Use lint-free wipes or one-click cleaners designed for your connector type (LC, SC, ST, or 2.5mm universal). Even a small amount of dust can reduce the signal by 1–5 dB, while clean connectors typically add only 0.2–0.5 dB of loss . 2. Match the Wavelength Set the optical power meter to the same wavelength as the signal being measured (e.g., 850 nm, 1310 nm, 1550 nm). Mismatched wavelengths can cause the photodiode to under-respond, lowering the measured power . 3. Use Proper Reference and Calibration Perform a reference measurement using a calibrated light source and launch cord. Set the meter to zero or reference mode to account for any baseline loss. Regular calibration ensures the meter reads accurately and consistently . 4. Minimize Insertion Loss Check the fiber link for bends, splices, or damaged sections that can attenuate the signal. Use high-quality patch cords and ensure all connections are properly seated. Reducing insertion loss directly increases the optical power reaching the meter . 5. Optimize Meter Settings Ensure the meter is in the correct measurement mode (absolute or relative power) and that the display units (dBm, dB, or W) are appropriate for your application. Some meters allow amplification or averaging of the signal to stabilize readings . 6. Verify Light Source Strength If possible, use a stronger or properly adjusted optical source. The meter can only measure the power that reaches it, so increasing the source output within safe limits will increase the reading . By following these steps—cleaning connectors, matching wavelength, calibrating the meter, minimizing insertion loss, and optimizing source strength—you can maximize the optical power reading and ensure accurate, reliable measurements in fiber optic networks .

Article Content

Optical power meter

OverviewPulse power measurementSensorsPower measuring rangeCalibration and accuracyExtended sensitivity metersCommon fiber optic test applicationsTest automation

Optical power meters usually display time-averaged power. So for pulse measurements, the signal duty cycle must be known to calculate the peak power value. However, the instantaneous peak power must be less than the maximum meter reading, or the detector may saturate, resulting in wrong average readings. Also, at low pulse repetition rates, some meters with data or tone detection may produce improper or no readings. A class of "high power" meters has some type of optical attenuating element

Related Video Reference

This video was associated with the source search result. Verify technical details against current product documentation and project requirements.

© 2026 ZITHA TECH SPECIALTY CABLES (Pty) Ltd - All rights reserved

Contact Us

Continue your research online:

Website: https://zithatech.co.za
Technical inquiry: https://zithatech.co.za/contact.html

This document is for preliminary research. Verify specifications against current standards, product documentation and project requirements.

© 2026 ZITHA TECH SPECIALTY CABLES (Pty) Ltd - All rights reserved