ZITHA TECH SPECIALTY CABLES (Pty) Ltd

Fiber optic array adhesive removal



Overview

Essentially you need to create a bond failure by getting the adhesive to fail. If you need to get the substrates apart, it will probably take some work using softening and separation methods. However, there are times when these strong bonds need to be undone. Whether for rework, repair, component recovery, or end-of-life. Diamond lapping films (polishing papers) are used to remove zirconia ferrule material, this is needed when a glass fiber breaks off below the ferrule surface. They are sold separately to allow better material. Using the proper adhesive in the assembly of fiber optic components not only saves time and expense, but also can improve reliability and performance. Adhesives for fiber optic components that perform well on glass, metal, ceramic and most plastic substrates provide excellent chemical and solvent. Adhesives for Fiber Array Assemblies NTT-AT Introducing the adhesives with high moisture resistance and excellent workability for fiber array assemblies Adhesives for Fiber Array High Moisture Resistance and Excellent Durability Can Be Polished For a Fiber Array, no peeling after 2,000 hours at. Master Bond offers an extensive line of epoxies and UV curing systems for use in fiber optics devices.



© 2026 ZITHA TECH SPECIALTY CABLES (Pty) Ltd - All rights reserved

Article Content

The Unsticking Challenge: How to Safely Remove Optical Adhesives

By leveraging our product knowledge and technical expertise, you can confidently manage your optical assemblies throughout their entire lifespan. Contact Incure today to discuss your optical

Step by Step Guide

This tutorial shows you the detailed step-by-step guide on on how to terminate an epoxy and polish SC connector onto 3mm jacketed fiber. Including fiber cable stripping, connector preparation, how to

Adhesives for Fiber Optics Assembly: Making the Right

Adhesive technology has always played a role in fiber optics assembly. Initially, epoxy technology was the method of choice, primarily in the connector market,

Fiber Optic Cleaning Guide | FS

The fiber optic cassette cleaner wipes away contaminants from the optical connector end face with ease. The cleaning tape does not produce dust and provides special cleaning strength while resisting

Adhesives for Fiber Array Assemblies NTT-AT

Fiber arrays are used for the input and output of optical waveguide devices. NTT-AT''s AT3925M, AT9390, AT9968, AT3727E and AT3728E epoxy-based optical

Epoxy Removal Methods and Strategies

Fiber Optic Center, Inc., (FOC), is an international leader in distributing fiber optic components, equipment, materials, and supplies known for helping customers make the best cable

Freespace Simulation Environment

FEATURES AND BENEFITS Bubbles and voids in uncured adhesives can be responsible for optical fiber cracks developed during the curing process. By using the centrifuge and therefore avoiding the

The FOA Reference For Fiber Optics

Fiber Optic Termination With Adhesive/Polish Connectors Adhesive/Polish Connectors Terminating optical fibers by attaching connectors with an adhesive

Fiber Optic Cable Glue: A Manufacturer''s Guide to Incure Adhesives

© 2026 ZITHA TECH SPECIALTY CABLES (Pty) Ltd - All rights reserved

Robust & Reliable Bonds: Beyond optical performance, Incure''s adhesives provide durable, long-lasting mechanical bonds. They offer excellent resistance to thermal cycling, humidity, and

Fiber Optic Cleaning Best Practices

Cleaning 1.25mm and 2.5mm Fiber Optic Backplane Connections using Precision Swabs The need to clean fiber optic connectors is well documented. The more

Fiber U Basic Skills Lab Workbook-termination

Fiber U Basic Skills Workbook Fiber Optic Cable Termination What You Will Learn: How to prepare cables for termination How to terminate fibers with basic adhesive/polish connectors and/or other

How to Terminate and Polish a Fiber Optic Connector

Instructions how to terminate optical fibers by attaching connectors with an adhesive, and polishing the ferrule. Termination procedures for single-mode and multimode Mountable Connectors using glue.

MATERIALS AND FABRICATION ISSUES OF OPTICAL FIBER ARRAY

Until now, soldering, laser welding and adhesive bonding methods have been employed for assem-bly of optical fiber array. Soldering process need for metallization and high heat loads that may af-fects the

Adhesives for Fiber Array Assemblies NTT-AT

As adhesives used for fixing the V-Grooves, AT3727E and AT3728E have realized price reductions while enhancing moisture resistance than conventional products with over 20 years more experience.

Adhesives for Fiber Optic Applications | MasterBond

Master Bond offers an extensive line of epoxies and UV curing systems for use in fiber optics devices. These products provide superior bonding strength and

Care of Optical Fibers During Splice Preparation

Splicing and termination procedures require the removal of a section of the optical fiber''s protective coating. It is crucial that the coating removal be accomplished carefully to minimize the impact on the

The FOA Reference For Fiber Optics

As your fingers reach the end of the fiber, gently grab the fiber and pull away from the connector and very slightly to the side. Now you are ready to polish. Most

Adhesives for Fiber Optic Assembly

© 2026 ZITHA TECH SPECIALTY CABLES (Pty) Ltd - All rights reserved

Out of the multitude of adhesives currently available, there are five families that are most commonly used in fiber optic assembly. Each of these families offers a unique combination of performance and

Contact Us

Continue your research online:

Website: https://zithatech.co.za
Technical inquiry: https://zithatech.co.za/contact.html

This document is for preliminary research. Verify specifications against current standards, product documentation and project requirements.

© 2026 ZITHA TECH SPECIALTY CABLES (Pty) Ltd - All rights reserved